# Work Order (Bid Form)

#### WORK ORDER INFORMATION

Work	Order	Name:
------	-------	-------

Work Order Type: Weatherization Audit Name: MADISON

### **CLIENT INFORMATION**

Client Name:

Address:

Client ID:

Alt. Client ID: 16016SW-1060

#### AGENCY INFORMATION

Agency: SWHRA

Agency Phone: (731) 989-5111

Fax:

Address: 1574 White AVE

Henderson, TN Email Address:

Agency Contact: Oliver, Jerry

Work Phone: Cell Phone: Email Address:

Company Name & Licens	se Number:
Contractor's Signature:	

#### COMMENT

NOTICE:

All work performed and material must meet all requirements as stated in the Southeast Weatherization Field Guide. It is the contractor's responsibility to pull all necessary permits required for the town or county where the work is being performed. No change order work shall be done until the change order has been approved and signed. If heater is required no air sealing should be done before heater is installed.

731-424-4433

Client Name: Client ID: Work Order (Bid Form)

DOE Weatherization Assistant

Alt. Client ID: 16016SW-1060

Work Order Name:

Report Run On: 5/25/2010

Version 8.5.0

Page 1 of 5

## Measures

	Measure 1 Infilt	ration Redctn			Component	's			Inspected
					Estimated			Actual	
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Construction Materials/Hardwar e	Seal breaker box and hole by breaker box,Seal hole in wall by water heater, Seal walls behind washer and dryer, Seal beam from sunken den to living room	Each	1					
2	Labor	Labor	Hour			,			PRO 1000 100 100 100 100 100 100 100 100 1
3	Construction Materials/Hardwar e	Seal wall in bedroom by behind tub, Seal ceiling around return air, Seal under bath vanity and wallin closet, Seal door jam between hall and bedroom	Each	1					
4	Labor	Labor	Hour		Transaction of the state of the				
5	Construction Materials/Hardwar e	Seal old flu in bedroomand closet in same bedroom, Seal crown molding in west living room. Seal exhaust vent over cook stove, Seal closet in hall around vent pipe	Each	1					
6	Labor	Labor	Hour						
7	Construction Materials/Hardwar e	Caulk all windows and replace broke glass in S1,S2 and E2 windows	Each	1		TO CONTROL OF THE STATE OF THE		The state of the s	
8	Labor	Labor	Hour		1				

	11.11.11.11.11.11.11.11.11.11.11.11.11.							
			) [			7		
			J L			] [		
			Measur	e Sub Total:		The second secon	Sub Total:	
Field Notes:	800 (100)				7			
Measure 2 DW	H Pipe Insulation	**************************************		Componen	ts			Inspecte
	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,							
Comment								
				Estimated			Actual	
Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
Insulation	DHW Pipe Insulation	Each	1	100				
	•			L		L	L	
2 Labor	Labor	Each	1		<u> </u>			
	Labor	Each	1					
	Labor	Each	1					
	Labor	Each	1				The state of the s	
	Labor	Each	1					
Labor  Other Detail	Labor			e Sub Total:			Sub Total:	

Measure 3 A	Attic Ins. R-30			Componen	ts A1			Inspected
Comment								
				Estimated			Actual	
# Material / Labor	•	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Insulation	Attic Insulation - Blown Cellulose - R-30	SqFt	1477					
2 Labor	Labor	Hour	1477					
3 Construction Materials/Hard e	Install attic access cover war	Each	1					
4 Labor	Labor	Hour			~~~			
Other Detail			,					
				0004314 01 174				
			Measur	e Sub Total:			Sub Total:	
Measure 4 S	torm Windows			Componen	ts E2,N4	,N1,S4	,E1 /	nspected
Comment								
				Estimated	RELEVEN VALLER STATES LANGUAGE LANGUAGE		Actual	
# Material / Labor	•	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Windows	Storm Window	Each	5					
2 Labor	Labor	Each	68.97					
Other Detail		passaciones de la company	·					
								the Invaded output,
	N		Measure	Sub Total:		S	Sub Total:	
Field Notes:								

Client Name: Client ID:

Alt. Client ID: 16016SW-1060

Work Order (Bid Form)

Work Order Name:

Report Run On: 5/25/2010

Version 8.5.0 Page 4 of 5

Measure 5 C	O Monitor is Needed		•	Componen	ts		1	nspected
Comment								
				Estimated			Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
Health and Safe     Items	ety CO monitor	Each	1					
2 Labor	Labor	Hour	1					
Other Detail								
			Measur	e Sub Total:	*		Sub Total:	
Field Notes:								
Measure 6 Pi Comment	ressureRelief Piping Need	ded		Component	ts		I	nspected
				Estimated			Actual	
# Material/Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
Health and Safe Items	ety Pressure relief piping	Each	1					
2 Labor	Labor	Hour	1				7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7	And and a second a
Other Detail								
			Measure	e Sub Total:		5	Sub Total:	
Field Notes:								
		Work Or	der Gra	nd Total:		Grand	d Total:	

Client Name: Client ID:

Alt. Client ID: 16016SW-1060

Work Order (Bid Form)

Work Order Name: Report Run On: 5/25/2010 DOE Weatherization Assistant Version 8.5.0

Page 5 of 5